





## MFD NON-COMPLIANCE REPORT # 30166-37

PART NAME: **COPPER HEAT SINK AND CHIN GUARD**  
PF/SA NO.: **26Q602 REV B**  
WORK ORDER NO.: **30166-37**  
VENDOR: **MFD/KLY**

DATE: **6/4/13**  
INSPECTOR: **K. CABAN**  
ENGINEER: **P. MONTANEZ** EXT.: **5461**  
ROUTE TO: **MFG SUPPORT**

### Reason For Non-Compliance:

1.



Engineer Signature: \_\_\_\_\_ Date: \_\_\_\_\_