



## MFD NON-COMPLIANCE REPORT # 30216-17

PART NAME: **BEARING PLATE 1**  
PF/SA NO.: **PF-391-124-44 R0**  
WORK ORDER NO.: **30216-17**  
VENDOR **MFD**

DATE: **6/12/13**  
INSPECTOR: **K. CABAN**  
ENGINEER: **JC CASTAGNA** EXT.:  
ROUTE TO: **EXP**

Reason For Non-Compliance:

Action (UAI,RWK,SCRIP)

1. Break Edges .005 - .015, there are burrs or sharp corners on all parts.

Engineer Signature: \_\_\_\_\_ Date: \_\_\_\_\_