



## NON-COMPLIANCE REPORT # 32435-2

PART NAME: COAX GASKET RING  
PF/SA NO.: PF-490-703-61 R2  
WORK ORDER NO.: 32435-2  
VENDOR HUMBOLDT INSTRUMENTS

DATE: 11/23/15  
INSPECTOR: K.CABAN/B.RUTLEDGE  
ENGINEER: K. FANT EXT.: 4466  
PLANNER:

### Reason for Non-Compliance:

### Disposition (UAI, Rework, Scrap, Other):

1. Diameter  $2.630^{+.003}_{-.001}$  measures between 2.6333 - 2.6357.

Engineer Signature: \_\_\_\_\_

Date: \_\_\_\_\_