



## NON-COMPLIANCE REPORT # 33073-126

PART NAME: YAG CRYSTAL MOUNT  
PF/SA NO.: PF-380-520-12 R1  
WORK ORDER NO.: 33073-126  
VENDOR PRO-TEK

DATE: 8/22/16  
INSPECTOR: K. CABAN  
ENGINEER: B. ARNOLD EXT.: 8534  
PLANNER: DIANNA

### Reason for Non-Compliance:

### Disposition (UAI, Rework, Scrap, Other):

1.  $\varnothing 1.004^{+0.001}_{-0.000}$  measures 1.0033 (-0.0007" out of tolerance).
2.  $\varnothing 1.210^{+0.005}_{-0.000}$  measures 1.2093 (-0.0007" out of tolerance).

Engineer Signature: \_\_\_\_\_

Date: \_\_\_\_\_