



Precision Measurement and Inspection

## NON-COMPLIANCE REPORT # 33073-128

PART NAME: SPACER  
PF/SA NO.: PF-380-508-18  
WORK ORDER NO.: 33073-128  
VENDOR: PRO-TEK

DATE: 8/24/16  
INSPECTOR: K. CABAN  
ENGINEER: B. ARNOLD EXT.: 8534  
PLANNER: DIANNA

### Reason for Non-Compliance:

1.  $\varnothing 1.002$   $+0.000/-0.002$  measures 1.0043 (+0.0023" out of tolerance).

### Disposition (UAI, Rework, Scrap, Other):

SCRAP PART, REMAKE

Engineer Signature: PER B. ARNOLD (FIT CHECK)

Date: 8/30/16