



## NON-COMPLIANCE REPORT # M-24902

PART NAME: X-BAND HYBRID FLANGE FEMALE  
PF/SA NO.: SK-NW-150331-2  
WORK ORDER NO.: M-24902  
VENDOR EDM DEPT INC.

DATE: 8/4/15  
INSPECTOR: K. CABAN  
ENGINEER: N. WHYNOTT EXT.:  
ROUTE TO: CUSTOMER

### Reason for Non-Compliance:

### Disposition (UAI, Rework, Scrap, Other):

1. Dim #20,  $0.050^{+0.010}_{0.000}$  measures 0.0495 – 0.0496 on all parts.
2. Dim #31,  $0.014 \pm 0.004$  measures 0.0062 – 0.0094 on all parts
3. Dim #32,  $R0.005 \pm 0.002$  measures 0.0015 on SN 102 only.

Engineer Signature: \_\_\_\_\_

Date: \_\_\_\_\_