MFD NON-COMPLIANCE REPORT # 5115

PART NAME:	**SUPPORT, CABLE HARNESS**	DATE:	**9/10/04**		
PF/SA NO.:	**LAT-DS-03598 Rev. 50**	INSPECTOR:	**K. CABAN**		
WORK ORDER NO.:	**2600177**	ENGINEER:	**J. CULLINAN**	EXT.:	**5034**
VENDOR	**OSV**	ROUTE TO:	**CUSTOMER**		

Reason For Non-Compliance:

Action (**UAI,RWK,SCRP**)

1. Height 0.590 ± 0.005 is oversized on all 3 parts by +0.005".

Engineer Signature: _____ Date: _____