

# Quindos Measuring Report



3D-Application Center

Description	PUMP CROSS	Customer	C. RAGO
Drawing Number	AAA09-501009	Serial Number	001
Remarks		Article Number	
Supplier	MFD	Delivery Date	
Delivery Note		Delivery Volume	
Lot Number		Lot Size	
Test Schedule		Sample Size	
Production Machine		Production Tool	
Production Date		Production Time	
Order	24930-2	Department	MET. QUALITY INSPEC
Inspector	kcaban	Inspection Date	25-SEP-2009, 12:44:32
Measuring Device	PMM 12 10 6 #496	Measuring Program	Quindos7 - V 7.1.9261-B
User Name	kcaban	WKP Name	NO\$NAME

Text	Eval.	Actual	Nominal	Up.To1.	Low.To1.	Act-Nom	Graphic
<b>PLA_16P255</b>		<b>PLA</b>					
FORM		0.01026					
Z		-16.20354	16.20500			-0.00146	
<b>PAR_16P255</b>		<b>PLA</b>					
PARALL		0.17438	0.00000			0.17438	
<b>DIA_OPP</b>		<b>CIR</b>					
FORM		0.01758					
X		0.96858	1.00000			-0.03142	
Y		0.04911	0.00000			0.04911	
<b>PLA_18P000</b>		<b>PLA</b>					
FORM		0.00527					
Y		15.92558	15.95000			-0.02442	
<b>DIA_TOP\$ROT</b>		<b>CIR</b>					
FORM		0.00903					
X		0.77613	1.00000			-0.22387	
Z		-8.07913	8.10000			-0.02087	
<b>PLA_5P500</b>		<b>PLA</b>					
Y		-5.48259	5.50000			-0.01741	
<b>PLA_6P500</b>		<b>PLA</b>					
FORM		0.03828					
Y		6.48443	6.50000			-0.01557	

Text	Eval.	Actual	Nominal	Up.To1.	Low.To1.	Act-Nom	Graphic
Date: 25-Sep-09, 12:44:32				NO\$NAME		Page 1 of 1	