








Date TLD monitors installed


6/3/2003

Date TLD monitors removed



B062 (ESB) Background:
 Located inside tall cleanroom near NW power center
 L6559537DP
 L6559533DP

B128 Background:
 Located N wall of work area near restroom
 6000711
 6001185
 L6559544DQ



Installation notes:

DateTLD monitors installed

6/3/2003

DateTLD monitors removed